

# Annexure D

## BUILDINGSAFETYCERTIFICATE

No. ~~2249~~ 1396

Date :- 07/08/23

It is certified that the existing building SANT NANDLAL SMRITI VIDYA MANDIR at JHATAWA KALAN ROAD, P.O:- MALISAR, Distt:- JHUNJHUNU RAJASTHAN - 331028 is having block(s)/ Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Ground + 3 Floor	N.A	N.A	N.A	N.A	N.A

The building is owned by SANT NANDLAL SMRITI VIDYA MANDIR have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of P.W.D – Jhunjhunu, Rajasthan Govt. on 29.12.2023 in the presence of Mr. VINOD KUMAR SAINI (Sr. Administrator) and that the building/premises is fit for occupancy for running school as per EE P.W.D Jhunjhunu Letter No. 2249 dated 04.01.2024 for a period of 3 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. In future, if the building has any issues relating to any cracks, collapse and leakage of water it should be reported to concerned Dept. and immediate action should be taken
2. Regular maintenance of Building and Plumbing works has to be taken up throughout the year.
3. The certificate will not be liable for any further construction/ addition/ alteration/ modification of Building/ Plumbing work will be taken place after issuance of this certificate.

Signature with Seal: [Signature]

Name: Rakesh Kumar

Designation: अधिसाधी अभियन्ता  
सा.नि.वि. खण्ड-हनुनू

Name&AddressofDepartment/ Office: PWD Jhunjhunu

( राकेश कुमार )  
अधिसाधी अभियन्ता  
सा.नि.वि. खण्ड-हनुनू

Raj.

कार्यालय अधिशाषी अभियन्ता सार्वजनिक निर्माण विभाग खण्ड, झुझुनु

क्रमांक... २२५९

दिनांक ५/१/२५

भवन सुरक्षा प्रमाण-पत्र

श्रीमान् मुख्य अभियन्ता सार्वजनिक निर्माण विभाग राजस्थान जयपुर के परिपत्र CE&AS/TA-1 /D&T/2017/139 Date 09.11.2017 एवं प्रशासनिक विभाग सानिवि राजस्थान जयपुर के संशोधित आदेश 7428/M/PWD/18 Dated 12.04.2018 की पालना में संत नन्दलाल स्मृति विद्या मंदिर, झटावा कलां रोड़ मलसीसर जिला झुझुनु (राज.) के भवन का निरीक्षण सहायक अभियन्ता सा.नि.वि. उपखण्ड अलसीसर द्वारा दिनांक 29.12.2023 को किया गया एवं उनकी प्रस्तुत रिपोर्ट के अधार पर उक्त भवन प्राकृतिक आपदाओं को छोड़कर सुरक्षित है।

यह भवन सुरक्षा प्रमाण-पत्र जारी किये जाने की दिनांक से तीन वर्ष के लिए मान्य होगा।

(शिव कुमार)  
अधिशाषी अभियन्ता  
सा.नि.वि.खण्ड-झुझुनु  
डी.डी.ओ. कोड-17256